




Connect to Mother Board

Connect to PC case(Optional)



The function of R26 is to avoid using USB A to C cables incorrectly, U5 will short VBUS to GND
When using USB C to C cables, there is no need to solder R26



Shenzhen Sipeed Techno. Co.,Ltd.	Date:
SCH:	Rev:
Page:	Id: